## TEXAS AVENUE CORRIDOR STUDY PROPERTY INVENTORY SURVEY FORM

***************************************		
Property ID:	R49140	

	GROUP 3
<b>Property Information</b>	HIRIORICA,
property address: <u>S COLLEGE</u>	<u>lve</u>
legal description: WINTER, BLOCK	C 4, LOT 1.1 & PT OF ALLEY
owner name/address: BIGLEY, JOHN F	
1309 S COLLEGE	
BRYAN, TX 778	
full business name:	
land use category:	Semi- type of business: Paking lot
current zoning:	occupancy status: <u>Caupied</u>
lot area (square feet): <u>2455</u> 5	frontage along Texas Avenue (feet):
lot depth (feet): sq. footage of building:	
	height (feet): # of stories:
	ng setbacks: □ yes □ no (if no, specify)
	cessible to the public:   yes   no   n/a
oossible historic resource: 🗆 yes 🗆 🗚	o sidewalks along Texas Avenue: □ <del>yes □ n</del> o
other improvements:   yes p no (specific points)	(pipe fences, decks, carports, swimming pools, etc.)
Freestanding Signs	
yes po	□ dilapidated □ abandoned □ in-u

## ☐ dilapidated ☐ abandoned ☐ intype/material of sign: # of signs: overall condition (specify): removal of any dilapidated signs suggested? □ yes □ no (specify) **Off-street Parking** improved: yes no parking spaces striped: yes no # of available off-street spaces: lot type: dasphalt concrete other gravel

overall condition: part as whalf part & white back

end islands or bay dividers: up yes pino:

landscaped islands: ☐ yes no

Curb Cuts on Texas Avenue	
now many: O curb types:   standard curbs   curb ramps   cu	rb cut closure(s) suggested? □ yes □
f yes, which ones:	
meet adjacent separation requirements: □ yes □ no meet opposite s	separation requirements:   yes   no
Landscaping	onerty? A yes no
yes no (if none is present) is there room for landscaping on the pr	oporty.
comments:	
Onto the Standard	
Outside Storage	
yes no (specify)	
dumpsters present: □ yes ☐ no are dumpsters enclosed: □ yes	- C/NO
Miscellaneous	
is the property adjoined by a residential use or a residential zoning district?	
yes no (circle one) residential use	residential zoning district
is the property developable when required buffers are observed?	
if not developable to current standards, what could help make this a develop	
If not developable to current standards, what could help make his a develop	able property.
accessible to alley:   yes no	
Other Comments:	
DAYKING lot for 1249139	
	<u> </u>